

STANDARD DEPARTURE ROUTES – INSTRUMENT (SID) TURKISTAN RWY 05

ARVAR 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn RIGHT on track 107° until intercept R077° TRK, proceed to
ARVAR R076.8°, D26.2 TRK.
Cross ARVAR at 7000 or above.

MAGOL 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn RIGHT on track 188° until intercept R148° TRK, proceed to
MAGOL R147.8°, D28.7 TRK.
Cross MAGOL at 7000 or above.

LARBA 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn RIGHT on track 210° until intercept R170° TRK, proceed to
LARBA R169.9°, D30.2 TRK.
Cross LARBA at 7000 or above.

RELRU 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn RIGHT on track 236° until intercept R196° TRK, proceed to
RELRU R195.6°, D32.5 TRK.
Cross RELRU at 7000 or above.

KARIM 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn RIGHT to TRK, after crossing TRK proceed on track 251° to
KARIM R250.9°, D35.3 TRK.
Cross KARIM at 7000 or above.

KUDUG 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn LEFT on track 247° until intercept R287° TRK, proceed to
KUDUG R287.5°, D31.7 TRK.
Cross KUDUG at 7000 or above.

GOBOR 1C

After take-off climb straight ahead to 2500 or above, at 6.9 NM TRK turn LEFT on track 272° until intercept R322° TRK, proceed to
GOBOR R322.5°, D21.8 TRK.
Cross GOBOR at 9000 or above.